



Touchscreen Ground Strap Retrofit Kit

(Hall P/N C-060-00009)

There is a manufacturing defect in the Monitor HT which may cause the touchscreen display to blank-out when static electricity builds-up. The problem is easily corrected by grounding the display to the stacker chassis with the enclosed kit(s). We strongly recommend that you make the modification to every Monitor HT in you mailroom. If additional kits are needed, please contact our customer service department.